



STEP 1 :

- EXCAVATE IN 1m DEPTH INCREMENTS
- STRIP TOP 1m OF EXCAVATED MATERIAL AND STOCKPILE SEPARATELY
- COMPLETE INTRUSIVE INVESTIGATION



STEP 2 - 3 :

- SPREAD AND SCAN EXCAVATED MATERIAL



STEP 4 :

- SCAN AT BASE OF EXCAVATION
- BACKFILL WITH SCANNED MATERIAL

