


Plans from The Hongkong Electric Company, Limited ("HK Electric")

of the signs \bigcirc or \bigcirc be found on the underground electricity cable plan provided in the vicinity of the work area, call 2814 3443 to contact HK Electric Call 2814 3443 if you do not have one. Should any for site inspection before commencement of any



Cable Alignment

cables and mark the underground electricity road surface before locating device to locate the alignment of commencement of work. the


3. Trial Holes

and depth of underground the exact position tools to locate Make use of hand electricity cables



4. Toroidal Active Detection

Determine and record the depth profile of the unexposed part of cable.



backfilling. For enquiry, call 2814 3443 warning tapes previously removed before Reinstate all protection slabs and

work in conformity with sound technical and engineering practice. The Hongkong Electric Co., Ltd. shall not be liable for any losses and/or damages suffered by any to protect underground services as stipulated in the latest version of Code of Practice of Excavation and Construction Work near Underground Electricity Cables issued by the whole or any part of the contents of this leaflet contractors arising out of or in consequence of their work taken or from reliance upon contractors must exercise due diligence and all reasonable care in carrying out their by Highways Department and other relevant legislative requirements. Moreover, the Conditions of Excavation Permit or Conditions of Emergency Excavation Permit issued 406) issued by Electrical and Mechanical Services Department, the latest version of on Working near Electricity Supply Lines in accordance with the provisions of the Electricity Supply Lines (Protection) Regulation under the Electricity Ordinance (Cap. The Hongkong Electric Co., Ltd., they should take all necessary precautionary measures to following the procedures set out in this leaflet and the General Practice on Execution This leaflet is intended for guidance only. Contractors are reminded that in addition